


## CHOGORI

## 1 Strip and prepare Cable.

1



## 2 Thread Seals Nut, Seals Ring, Clamp Ring and Gasket onto the cable.

2



## 3 Solder wire

3



## 4 Assemble Gasket into Clamp ring: Gasket Direction (Flat Surface to Housing)

4




## 5 Assemble Clamp Ring to Housing

5



## 6 Put Seals Ring to the end of Clamp Ring.

6



## 7 Assemble Seals Nut and Clamp Ring.

7

