


**CHOGORI**


**1 Strip and prepare Cable.**

1



**2 Thread Seals Nut, Seals Ring, Clamp Ring and O-Ring onto the cable.**

2



**3 Solder wire.**

3



**4 Assemble O-Ring into Clamp ring.**

4



**5 Assemble Clamp Ring to Housing.**

5



**6 Put Seals Ring to the Clamp Ring.**

6



**7 Assemble Seals Nut and Clamp Ring.**

7

